

APPENDIX F - PLUGGING AND ABANDONMENT PLANS

Upon completion of injection activities the well(s) shall be abandoned according to State and Federal regulations to ensure protection of Underground Sources of Drinking Water.




Figure 9. Schematic of general plugging and abandonment plan for proposed wells WD-1 – WD-5.